December 15, 2009 12:52:14 PM

**Required Date: 23/12/2009** 

Item ID: **Revision ID:**  D2580-1

Accept

Setup Start

Stop



205 Skidtube bent detail

Item Name: **Start Date:** 

15/12/2009

QC:

Start Qty: 2.00 Req'd Qty: 2.00

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

SPC (Y/N):

Date:

Date:

Start

Stop

Sequence ID/ Work Center ID

**Draw Nbr** 

**Operation** Description

**Revision Nbr** 

Date:

Set Up/. **Run Hours**  Draw Number Draw

Accept

Run

D2580

Rev D

100

HandFinish

Memo

0.00

0.00

Hand Finishing

1- Inspect mat'l D2500-1-190 for damage.

2- Chemical Conversion Coat as per OSI 005 4.1

101

QC3- Inspect Part Finish

0.00



Memo

0.00

Quality Control

Rev.

Code

Qty

Reject Qty

Reject Number

Stamp

Dart Aerospace Lt
-------------------

	•									~
W/O:			W	ORK ORDER CHAN	GES			-w.		
DATE	STEP	PRO	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					į.					
			·							
		· · · · · · · · · · · · · · · · · · ·	<u> </u>						we	
Part No		PAR #:								
	Re	esolution:							Date:	
NCR:			WORK OR	DER NON-CONFORM	IANCE	(NCR	)			
DATE	STEP	Description of NC					cation	Approval	Approval	
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date		on C	Chief Eng	QC Inspector
	ļ								·	
									-	
:										
			,							
									'	



December 15, 2009 12:52:14 PM

Item ID:

D2580-1

Accept

Setup Start

**Revision ID:** 

Item Name:

205 Skidtube bent detail

**Start Date:** 

15/12/2009

Start Oty: 2.00

**Required Date: 23/12/2009** Req'd Qty: 2.00



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan: Date:

Tooling:

SPC (Y/N):

Date:

Date:

Start



Stop

Sequence ID/ **Work Center ID**  Operation Description

Set Up/ **Run Hours**  Draw Number

Draw Plán Code Rev.

Accept Qty

Reject **Qty** 

Run

Reject Insp. Number Stamp

110

Skidtubes Skidtubes

Memo

QC: Date:

0.00

0.00

1-Drill pilot holes using drill jig DT 8149 (Do not use cutting fluid)

2-Open holes to 0.500" as per Dwg D2580 without cutting fluid

3-Deburr and blow out all chips from inside of tube

4-Bond web in place per QSI 015.

A/R Sikaflex-291 batch: 112 395 Sikaflex expire date:

130

QC5- Inspect part completeness to step on W/O

0.00

Memo

0.00

Quality Control

W/O:		WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector						
							٠.						
							, ,						
							**,*						
							2						

Part No:		PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed	d:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B		Verification	Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto				
-							-					
. "												
	·				ļ							
						-						
		1			ı	1	I	1				

### Work Order ID 54647



Page 3

December 15, 2009 12:52:14 PM

Item ID:

D2580-1

Accept

Setup Start

Stop

**Revision ID:** 

Item Name:

205 Skidtube bent detail

Start Date:

15/12/2009

Start Qty: 2.00

Operation

Description

Required Date: 23/12/2009 Req'd Qty: 2.00

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

Date:

**Tooling:** 

Date:

Start Run



QC:

Date:\_

SPC (Y/N):

Set Up/

**Run Hours** 

Date:

Stop

Sequence ID/ **Work Center ID** 

140

Packaging Packaging

Memo

Memo

Identify as per dwg & Stock Location

0.00

0.00

Draw Number

Draw Rev.

Plan Code

Accept Qty

Reject Qty

Reject Insp. Stamp Number

150

**Quality Control** 

QC21- Final Inspection - Work Order Release

0.00

0.00

Dart Aeı	ospace	Ltd					••	13
W/O:			WORK ORDE	R CHANG	ES			
DATE	STEP	PROC	EDURE CHANGE		Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
·		· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·				
-				; ;				
Part No	•	PAR #:	Fault Category:		_ NCR: Yes	No DQA:	Date:	
	Re	esolution: Disposition:				losed:	Date: _	
NCR:		W	ORK ORDER NON-C	ONFORM	ANCE (NC	R)		
DATE	STEP	Description of NC	Corrective A	ction Sect	tion B Sign	& Verification	Approval	Approval OC Inspector

NCR:		WORK ORDER NON-CONFORMANCE (NCR)											
	T	Description of NC		Corrective Action Section B	Verification	Approval	Annroval						
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector					
						•							
		1											
								- Parket and the second					
				. •		-							
				•									

### **Picklist Print**

December 15, 2009 12:52:18 PM

Work Order ID: 54647

Parent Item:

D2580-1

Parent Item Name: 205 Skidtube bent detail

Manufactured

**Comments:** 



Start Date: 15/12/2009

Required Date: 23/12/2009


Page 1

Start Qty: 2.00

Required Qty: 2.00

	eplacement em ID	Mfg/ Purch	Bin Item	Primary Location	Last & Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2500-1-190		Manufactured	No				Each	104.0000	2.0000			

Ext'n - I' Beam Tube 4"



D2596

Web, 205 Skidtube

Warehouse Loc Qty Location Main Warehouse LG

Loc Code

53263


<b>Dart A</b>	erospa	ace Ltd
---------------	--------	---------

W/O:			WORK ORDER CHANGES										
DATE	STEP	PF	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
						-							
							·						
			•			٠.							
Part No	):	PAR #:	Fault Category:	NCR: Yes	No DQ	<b>A</b> :	Date:						

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B		Verification	Approval Chief Eng	Approval QC Inspector				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C						
•												
					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							



DESIG	##	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECK	(ED,	APPROVED	DRAWING NO.	REV. D
	*	<b> </b> #	D2580 SHEET	1 OF 3
DATE		<u> </u>	TITLE	SCALE
07.0	2.27		205 SKIDTUBE ASSEMBLY	NTS
Α		96.09.16	NEW ISSUE	
В		96.12.02	AS MANUFACTURED	
С		98.08.26	REDRAWN, INCLUDED DEO 9094/90	97
D		07.02.27	CHANGE TO SS WEARPLATES AND GASKETS, INCLUDE DEO 9124/9183	;



QTY	QTY	Part Number	Description
-041	-045		
L X		D2580-041	SKIDTUBE ASSEMBLY
	Χ	D2580-045	SKIDTUBE ASSEMBLY
1	11	D2500-1-190	EXTRUSION
1	1	D2576-3	STEP
20	24	D2579	CROSS BOLT SPACER
16	16	D2594-1	PLUG
16	16	D2594-3	O-RING
1	1	D2596	205 WEB
1	1	D2855	AFT CAP
1	1	D3564-5	WEARSHOE
1	1	D3564-9	WEARSHOE
1	1	D3564-11	WEARSHOE
. 1	1	D3564-13	WEARSHOE
2	2	D3566-1	GASKET
1	1	D3566-5	GASKET
1	1	D3566-13	GASKET
50	50	ALS7-1032-130	INSERT
ľ		or AKS7-1032-130	
	1	or AKS4-1032-130	
		or AELS-1032-130	
50	50	AN3C4A	BOLT
2	2	AN3-5A	BOLT
50	50	AN960C10L	WASHER
2	2	AN960JD10L	WASHER

SHOP COPY
RETURN TO
REGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO 544,447


#### **GENERAL NOTES:**

- 1) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 2) ALL DIMENSIONS ARE IN INCHES
- 3) INSERT D2596 WEB TO LOCATION SHOWN OFF AFT END OF SKIDTUBE AND BOND WEB INTO OUTER TUBE WITH NON-STRUCTURAL SIKAFLEX-241 ADHESIVE PER DART QSI 015 BEFORE BENDING. ENSURE HOLES LINE-UP.
- 4) BEND AS A SMOOTH RADIUS STARTING WITH A MAXIMUM CENTERLINE RADIUS OF 60 AND ENDING WITH A MINIMUM RADIUS OF 30. A MAXIMUM REDUCTION OF 0.200 IN DIAMETER IS ALLOWABLE IN THE BENT PORTION OF THE TUBE.
- 5) USE DART DRILL TEMPLATE TD2577-205 TO LOCATE AND DRILL Ø0.297 HOLES FOR WEARSHOE INSERTS. INSTALL ALS7-1032-130 PER SECTION D-D (50 PLACES) AFTER FINISH. INSTALL AN3C4A BOLTS AND AN960C10L WASHERS WITH SIKAFLEX-241/-291.
- 6) WELDING TO BE DONE PER DART QSI 004.
- 7) FINISH:
  - \$ SEE NOTES ON
    PAGE 2 FOR D2580-041 AND
    PAGE 3 FOR D2580-045
- 8) INSERT D2594-1 PLUG C/W D2594-3 O-RING IN HOLES MARKED 'P' (BOTH SIDES OF TUBE) AFTER FINISH (16 PLACES).


Copyright @ 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Duit Au	ospace	Liu							′ •
W/O:			WO	RK ORDER CHANG	GES				
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approvai Chief Eng / Prod Mgr	Approval QC Inspector
		; *							
Part No:		PAR #:	Fault Cate	gory:	_ NCR: Yes	No <b>DQ</b>	A: Date:		
Resolution:			Disposition	_ QA: N/C C	losed:	_ Date:			
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC		tion B	Veritics		Approval	Approval QC Inspector	
DATE	Section A		Initial Action Description Chief Eng Chief Eng		Sign Date	& Sect	ion C		Chief Eng
	i i								
								i	



									7			
W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	PROCEDURE CHANGE				Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		·										
Part No:PAR #:		PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:			Date:				
		esolution:	Disposition				Date:					
NCR:		V	VORK ORDE	ER NON-CONFORMA	NCE (NC	R)						
DATE	STEP	Description of NC		n B	Verific	cation	Approval	Approval				
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Secti	ion C	Chief Eng	QC Inspector			
		,			-							



W/O:			W	ORK ORDER (	CHANGES					
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
. بر	<i>!</i> **	<del>*</del>								
ge <sup>c</sup>		·								
Part No	•	PAR #:	Fault Cate	egory:	NC	R: Yes	No DQA		Date:	
			Disposition: Q							
NCR:			WORK ORE	ER NON-CON	FORMANCE	(NCI	R)			
DATE	STEP	Description of NC Section A	Corrective Action Initial Action Desc Chief Eng Chief Eng		escription Sign &			ation on C	Approval Chief Eng	Approval QC Inspector
*										
		*								
			*						,	